

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

- Date _____ Initials _____
- ___ Determined Eligible-National Register
 - ___ Determined Not Eligible - National Register
 - ___ Determined Eligible - State Register
 - ___ Determined Not Eligible - State Register
 - ___ Need Data
 - ___ Contributing to eligible National Register District
 - ___ Noncontributing to eligible National Register District



I. IDENTIFICATION

- 1. Resource number: **5PE.5646**
- 2. Temporary resource number: **077**
- 3. County: **Pueblo**
- 4. City: **Pueblo**
- 5. Historic building name: **Central Assembly of God Church**
- 6. Current building name: **Salvation Army Community Center**
- 7. Building address: **520 W 13th Street**
- 8. Owner name: **Salvation Army**
- Owner organization:
- Owner address: **119 W 6th Ave**
Pueblo, CO 81003

Parcel number(s):

525419013

44. National Register eligibility field assessment:	<input type="checkbox"/> Individually eligible	<input checked="" type="checkbox"/> Not eligible	<input type="checkbox"/> Need data
Local landmark eligibility field assessment:	<input checked="" type="checkbox"/> Individually eligible	<input checked="" type="checkbox"/> Not eligible	<input checked="" type="checkbox"/> Need data

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION

9. P.M.: **6th** Township: **20S** Range: **65W**
SW 1/4 of **NE** 1/4 of **NW** 1/4 of **SE** 1/4 of Section **25**
10. UTM reference zone: **13**
 Easting: **533787** Northing: **4236603**
11. USGS quad name: **Northeast Pueblo** Scale: **7.5**
 Year: **1961 (Photorevised 1970 and 1974)**
12. Lot(s) : **Lot H, I, J, K, and L of Elizabeth Place Subdivision of the north half of Block 37**
 Addition: **County Addition** Year of addition: **1869**
13. Boundary description and justification:
The boundary, as described above, contains but does not exceed the land historically associated with this property.
 Metes and bounds exist:

III. ARCHITECTURAL DESCRIPTION

14. Building plan (footprint, shape): **T-Shaped Plan**
 Other building plan descriptions:
15. Dimensions in feet (length x width): **2,700 square feet (per story)**
16. Number of stories: **2**
17. Primary external wall material(s): **Concrete/Concrete Block** Other wall materials:
Wood/Vertical Siding
18. Roof configuration: **Flat Roof**
 Other roof configurations:
19. Primary external roof material: **Synthetic Roof/Rubber Roof**
 Other roof materials:
20. Special features: **Porch**
21. General architectural description:

Oriented to the north, this building rests on a high, cream-painted concrete foundation. Basement windows, which appear in bands, are frosted, single-light fixed frame. A deep concrete-block well lines the windows on the east elevation. Because of the slope of the lot, descending east to west, the west elevation of the basement is entirely exposed. Cream-painted concrete blocks comprise the walls. The rest of the windows along the side elevations open at the second story level and are frosted, single-light fixed frame. Between these windows and the basement windows are spandrels of brown-painted, vertical wood siding. There are three bays per side. Windows on the north ends of the east and west elevations are 3-light casement, with cream-painted steel frames. Dominating the front (north) façade are large, plate-glass windows. A flat-roofed porch spans most of the façade and extends outward to the west. The porch consists of a high, ornamental concrete-block wall. Anchored to the wall are paired, brown-painted porch supports, which are 4-by-8-inch boards. The principal doorway opens east of center in the façade, beneath the porch. Concrete steps approach it from the west and a concrete ramp from the east. The doors are paired, plate-glass, in tan-painted steel frames. A 2-light, plate-glass transom is above them. All other doorways host tan-painted, metal slab doors. They open in the north and south ends of the east elevation, and south of center in the west elevation, providing direct access into the basement. A tan-painted, wood slab door opens in the second story of the north face of the southeast-facing, inside corner. It provides access to a steel staircase. A large, 2-piece, bronze plaque, depicting the seal of the Salvation Army, is attached to the east end of the façade. A rubber membrane roof covers the flat, which a parapet lines at its north end. The porch roof has broadly overhanging, canted eaves.

22. Architectural style:

Architectural Inventory Form

Page 3

Modern Movements

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses and commercial buildings. Most of the houses here have an unusually deep setback from West 13th Street, the busy, principal east-west thoroughfare through this area. This property is situated on the south side of West 13th Street, between 508 West 13th Street to the east and 1214 North Elizabeth Street to the west. Macadam parking lots flank the east and west sides of the building, and the property lacks any landscaping.

24. Associated buildings, features or objects: **No associated buildings identified.**

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: **1956**
 Source of Information: **Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.**
26. Architect: **unknown**
 Source of information:
27. Builder: **unknown**
 Source of information:
28. Original Owner: **Central Assembly of God Church**
 Source of information: **Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.**
29. Construction history:
According to Pueblo County Tax Assessor records, this building was constructed in 1956. Historical records corroborate this date. This building has not been notably altered since its construction.
30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): **Church**
32. Intermediate use(s): **Organizational**
33. Current use(s): **Organizational**
34. Site type(s): **Community Center**
35. Historical background:
The first occupant of this building, completed in 1956, was the Central Assembly of God Church. The congregation remained here until 1983-84, when the Pueblo corps of the Salvation Army, organized in 1888, purchased the property to use as its headquarters and community center. Previous to this time, the Salvation Army was located at 110 East 10th Street. The organization sold its former headquarters to the City of Pueblo, which razed the building in 1985. The Salvation Army's new facility on West 13th Street provided the organization with ample office, dining, kitchen, and office space to expand its community outreach programs. By 1984, the organization fed 30 to 40 people nightly in its kitchen. In mid 1990s, the Salvation Army moved to 119 West 6th Street, but it continues to operate this building as a charity distribution center.
36. Sources of information:
Pueblo County Office of Tax Assessor. Property information card [internet].
Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Architectural Inventory Form

Page 4

"History is Uncovered as Building Falls." Pueblo Chieftain, 31 October 1985, p. 3B.

Herman, Chuck. "Just a Little Help and Grit." Pueblo Chieftain, 29 October 1984.

"New Commander has Big Plans." Pueblo Chieftain, 11 August 1984.

Tidswell, Jennifer. "Salvation Army Came to Pueblo 100 Years Ago this Summer." Pueblo Chieftain, 27 June 1987.

Architectural Inventory Form

Page 5

VI. SIGNIFICANCE

37. Local landmark designation: Yes No

Designation authority:

Date of designation:

38. Applicable National Register criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history.
- B. Associated with the lives of persons significant in our past.
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- Qualifies under Criteria Considerations A through G (see manual).
- Does not meet any of the above National Register criteria.

Pueblo Standards for Designation:1a. History Have direct association with the historical development of the city, state, or nation; or1b. History Be the site of a significant historic event; or1c. History Have direct and substantial association with a person or group of persons who had influence on society.2a. Architecture Embody distinguishing characteristics of an architectural style or type; or2b. Architecture Be a significant example of the work of a recognized architect or master builder, or2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;2d. Architecture Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or3c. Geography Make a special contribution to Pueblo's distinctive character.Not Applicable Does not meet any of the above Pueblo landmark criteria.39. Area(s) of Significance: **Not Applicable**40. Period of Significance: **n/a**41. Level of significance: National: State Local

Architectural Inventory Form

Page 6

42. Statement of significance:

Because this property is less than 50 years old and does not meet any of criteria considerations A through G, it is ineligible for listing in the National Register of Historic Places. Moreover, the architectural and historical significance are not to the extent that the property would qualify for individual listing in the Colorado State Register of Historic Properties or as a City of Pueblo landmark. Given its age, the property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register eligibility field assessment: Individually eligible Not eligible Need data
Local landmark eligibility field assessment: Individually eligible Not eligible Need data
45. Is there National Register district potential? Yes No
- Discuss: **Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.**
- If there is National Register district potential, is this building contributing: Yes No N/A
46. If the building is in existing National Register district, is it contributing: Yes No N/A

VIII. RECORDING INFORMATION

47. Photograph numbers): **CD-ROM Photo Disc: North Side Photos**
File Name(s): 13thstw520
- Negatives filed at: **Special Collections**
Robert Hoag Rawlings Public Library
100 East Abriendo Avenue
Pueblo, CO 81004-4290
48. Report title: **Pueblo North Side Neighborhood Survey**
49. Date(s): **06/27/05**
50. Recorder(s): **Adam Thomas**
51. Organization: **Historitecture, L.L.C.**
52. Address: **PO Box 419**
Estes Park, CO 80517-0419
53. Phone number(s): **(970) 586-1165**

Architectural Inventory Form


Page 7

SITE SKETCH MAP



Architectural Inventory Form

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)